


## Standard Operation Measurement

### Dielectric measurement by LCR

1. Press the main power button on the left corner of the LCR.
2. **Set up.**
  - a) Connect the test fixture<sup>1</sup> to the machine (Agilent 16334 A).
  - b) Insert the socket axial<sup>2</sup> into the test fixture.
3. **Calibration.**
  - a) Press **MEAS SETUP** and choose CORRECTION to enter correction page.
  - b) Use an insulating spacer to separate the two electrodes in the box holder. Move CURSOR arrow keys to the OPEN field (shown as "OPEN: OFF" or "OPEN: ON"). Press MEAS OPEN.
  - c) During the OPEN correction measurement, ABORT key is used to stop an OPEN correction data measurement.
  - d) After the measurement, press ON to perform the OPEN correction calculations on subsequent measurements (or press OFF not to perform the correction data)
  - e) Remove the spacer and connect two electrodes with the shorting bar<sup>3</sup>. Move CURSOR to the SHORT field and press MEAS SHORT.
  - f) After the measurement, press ON to perform the SHORT correction calculations on subsequent measurements (or press OFF not to perform the correction data).
4. **Taking Single Measurements**
  - a) Insert the two wires<sup>4</sup> into the socket axial and secure your sample between them, ensuring proper contact.
  - b) Press **DISPLAY** to enter display page.
  - c) Use CURSOR arrow keys to move the cursor to the FUNC field and choose the proper measurement function such as Cp – D, Cp - Q.
  - d) Move the cursor to the FREQ. field and change the test frequency. The frequency range is from 20 Hz to 1 MHz.
5. **Taking a Sweep of Measurements**
  - a) Press the MEAS SET-UP key
    - i. Use the soft keys to select LIST SET UP
    - ii. Use CURSOR arrow keys to move the cursor to the first blank line below the FREQUENCY field
    - iii. Input your desired frequencies in a column, one below the other using the unit (Hz, KHz, or MHz) from the soft keys
  - b) Press the DISPLAY FORMAT key
  - c) Press LIST SWEEP on the soft keys, measurements should appear
  - d) To return to the regular single measurement screen, press the MEAS DISPLAY key
6. After the measurement, turn off the main power and remove the holder.

## Agilent 16334 A



### Connection Point




### 1. Test fixture



2. Socket axial



3. Shorting bar



4. Wires



<u>Symbol</u>	<u>Parameter Name</u>	<u>Equation</u>	<u>Definition</u>	<u>Notes</u>
Z	Impedance	$Z=R+jX$ $Z=V/I$		
R	Resistance	$R=Z\cos\theta$	Resistance is the real part of the impedance	
X	Reactance	$X=Z\sin\theta$	Reactance is the imaginary part of the impedance	
Y	Admittance	$Y=G+jB$ $Y=1/Z$		
G	Conductance	$G=1/R$	Conductance is the real part of the admittance	
B	Susceptance	$B=1/X$	Susceptance is the imaginary part of the admittance	
C	Capacitance	$C= \epsilon_r \epsilon_o (A/d)$	capacitance is the ability of a body to hold an electrical charge	$\epsilon_r = C/[ \epsilon_o (A/d)]$ $P= \epsilon_o (\epsilon_r -1) E$
L	Inductance	$v(t)=-L(di/dt)$	change in the current flow that induces a voltage that opposes the change in current	
D	Dissipation Factor	$D=1/Q$	(Loss Tangent)	
Q	Quality Factor	$Q=\omega*(\text{EnergyStored}/\text{PowerLoss})$ $Q= X/R $ $Q= \tan \phi $	compares the frequency a system oscillates to the rate it dissipates energy	
$\phi$	Phase Angle		The angle the voltage sine curve leads or lags the current sine curve	
$\Theta$	Phasor Angle	$\theta=\omega t$		